



November 19, 2007

Ms. Jennifer Hale
Weyerhaeuser Company
P.O. Box 9777
Mail Stop WTC-2G2
Federal Way, WA 98063-9777

Subject: 12th Street Landfill – Emergency Action
Status Update Report

Dear Jennifer:


This letter presents activities performed as part of the 12th Street Landfill emergency action in Plainwell, Michigan, between October 15 and November 7, 2007. Construction of the emergency action activities was completed including the following:

- Completed installation of stone riprap along shoreline.
- Removed trees on north and south end of landfill which had visual residuals within root system.
- Placed topsoil along access road and east face of landfill.
- Placed silt fence system between access road area and stone riprap.
- Placed turf reinforcement mat along access road and face of landfill.
- Covered sediment containment pad with general fill.
- Covered east face and top of landfill with general fill material.
- Emptied soil drums within containment pad, crushed and buried drums.

Photographs of the above activities are attached. If you have any questions regarding RMT's services, please contact me at 262-879-1212.

Sincerely,

RMT, Inc.



James L. Hutchens
Sr. Project Manager

cc: Michael Berkoff, USEPA
Jeff Keiser, CH²M Hill
Paul Bucholz, MDEQ

E:\WPMLW\PJT\00-05131\03\L000513103-009.DOC

Photographic Log

Client Name: Weyerhaeuser Company		Site Location: Plainwell, Michigan	Project No.: 00-05131.03
---	--	--	------------------------------------





Photo No. 1	Date 10/26/07	
Description Empty soil drums within containment area		

Photo No. 2	Date 10/26/07	
Description Containment pad after placement of soil drum material		

Photographic Log

Client Name: Weyerhaeuser Company		Site Location: Plainwell, Michigan	Project No.: 00-05131.03
Photo No. 3	Date 11/2/07		
Description Shoreline and access road looking north			
Photo No. 4	Date 11/2/07		
Description Access area looking north			

Photographic Log

Client Name: Weyerhaeuser Company		Site Location: Plainwell, Michigan	Project No.: 00-05131.03
---	--	--	------------------------------------



Photo No. 5	Date 11/2/07	
Description Top of landfill looking northwest		

Photo No. 6	Date 11/2/07	
Description Containment pad area with general fill cover		

Photographic Log

Client Name: Weyerhaeuser Company		Site Location: Plainwell, Michigan	Project No.: 00-05131.03
---	--	--	------------------------------------



Photo No. 7	Date 11/7/07	
Description Top of landfill looking northeast		

Photo No. 8	Date 11/7/07	
Description Top of landfill looking east		